

TOP SECRET

BX 6739

25X1A

IN 80668

OPS 1-10

DB

TOP SECRET 160620Z CITE [ ] 163

25X1A

IMMEDIATE [ ] INFO IMMEDIATE [ ] ROUTINE

A. BX 6739

B. FILM EVALUATION REPORT

C. I/F/3897/67RTS

D.

E.

F.

G. (1) GOOD

(2) GOOD WITH EXCEPTION NOTED IN ITEM I.

(3) MEDIUM

(4) GOOD

(5) OPERATIONAL

(6) NORMAL

H. DISPOSITION:

1. 0 NEG AND 3 DUPE POS FORWARDED TO NATIONAL CUSTOMERS.

TOP SECRET

IN 80668 [ ] 1163)

T O P S E C R E T

PAGE 2

2. 6 DUPE POS AND 2 DUPE NEG FORWARDED TO THEATER CUSTOMS.

1. NORMAL START-UP AND SHUTDOWN WITH CAGING & SHUTTLE MOTION

FOR INITIAL 12 FRAMES AND LAST 14 FRAMES. RECYCLE AT FRAME 25X1D

25X1D [ ] REF H-5433 BEGINNING AT FRAME [ ] AND EXTENDING TO 5X1!

25X1D 5X1! FRAME [ ] THE FWD FRAMES ARE UNDEREXPOSED BY APPROXIMATELY

2 F STOPS. A VERTICAL MINUS DENSITY STREAK WAS NOTICED 16" FROM

DATA CHAMBERS IN AFT FRAMES AND 1 1/4" FROM INTERIOR EDGE OF 25X1D

FWD FRAMES, BEGINNING WITH FRAME [ ] AND CONTINUED FOR

APPROXIMATELY [ ] FRAMES. INTERMITTENT PLUS DENSITY LINE 2" 25X1D

FROM TRAILING EDGE ON ALL FRAMES. BANDING OCCURRED IN FRAMES [ ] TO 25X1!

25X1D 5X1! [ ] MINUS DENSITY LINES OCCURRED 3/4" AND 4" FROM EDGE IN AFT

FRAMES. 1/2" MINUS DENSITY STREAKS WERE EVIDENT ON BOTH EDGES

OF FILM THROUGHOUT MISSION. A YELLOW DISCOLORATION AND MINUS

DENSITY SPOTS WERE NOTICED THROUGHOUT THE MISSION WITH STREAKS

25X1D 1 OCCURRING FROM FRAME [ ] DISCOLORATION STREAKS AND SPOTS

WERE NOTED ONLY ON MISSION STOCK AND NOT ON PRESPLICED STARTUP

AND SHUTDOWN CONSISTING OF 300 FT OF MATERIAL ON EACH END OF

MISSION. MINOR HANDLING SCRATCHES ARE EVIDENT INTERMITTENTLY

THROUGHOUT MISSION.

T O P S E C R E T TOR 162822Z DEC 67

T O P S E C R E T